
09/912,406 Lewis et al. 1/30








FIG. 1B



The second of the second secon







FIG. 40






FIG. 5B




FIG. 6A






FIG. 6B

And the state of t



The state of the s







FIG. 9






FIG. 11

THE STATE OF THE PARTY OF THE STATE OF THE S




FIG. 13




FIG. 14






FIG. 15











FIG. 18A












THE THE WAS TH



:IG: 19




FIG. 20B





FIG. 20A



Operating Mode	Pressure Relief Valve	Approximate Air Pressure
System Error	Open	Zero
New Ink System Installed— Air Purge From Ink Tubes	Open ∆/Closed	1.5 psi
Prime Printheads With Positive Ink Pressure	Open ∆/Closed	.2 psi
Replace Printhead	Open	Zero
Replace Ink Cartridge	Open	Zero
Normal Printing	Closed	2.5 psi
Overnight Non-use	Open	Zero

FIG. 23